UI Bulletin #135c

Subject:	Turn Signals Engage When Depressing the Brake Pedal
Models Years Affected:	2017 - SOP to H1129315
Models Affected:	Chevrolet Express/GMC Savana Cut-away Vans with Separated Rear Stop/Turn Signals (V4D)
Origination Date:	October 17, 2016
Revision Date:	October 27, 2016

ADVISORY:

This UI Bulletin is being created using information contained in General Motors Preliminary Information Bulletin 16-NA-345 V2

Condition/Concern:

Some customers may comment that the turn signals engage when pressing on the brake pedal.

Cause:

This condition may be caused by a software anomaly.

Correction:

- For vehicles without UY7, update the body control module (BCM) with the latest software. Refer to *Body Control Module Programming and Setup in SI*.
- **DO NOT** perform this bulletin on vehicles with UY7 RPO. This change will result in the loss of stop lamp functionality for the trailer lamps if performed. Engineering is developing a solution for these vehicles.

Note: The solution will not be a SW solution. The UY7 (trailering capability) will either need to be removed or the vehicle will need to be rewired to retain proper trailering operation.

Warranty Information:

Dealers should refer to Bulletin 16-NA-345 for applicable warranty labor operation and time

Disclaimer: GM Upfitter Integration Technical Bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service and/or modification of a vehicle. These properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. Contact GM Upfitter Integration for information on whether the information is applicable your vehicle.